



Series DM DigiMag® Differential Pressure Transmitter

QUICK START GUIDE

1. **Mount** on surface or in panel using provided screws and mounting lugs.
2. **Attach** wires following diagram on reverse side.
3. **Set** zero calibration. Apply zero pressure to both pressure ports and press the zero button for 3 seconds.
4. **Scan** QR code with smart device to open the product web page for additional resources.




WIRING INFORMATION



SERIES DM
PRESSURE
TRANSMITTER

POWER
SUPPLY
10-35 VDC



Panel mount

Printed in U.S.A. 9/21
FR# 444630-00

©Copyright 2021 Dwyer Instruments, Inc.