




THIS EQUIPMENT HAS A ONE YEAR LIMITED INARRANTY WHICH COVERS DETECTIVE MATERIAL AND WORKMANSHIP. IT IS THE USERS RESPONSIBLE-ITY TO TRAIN THEIR EMPLOYEES IN THE PROPER HANDLING AND LARRING OF THIS PORTABLE TANK AND ITS CONTINUES AND TO INSINE PRODUCT

ALL OF THESE PROCEDURES ARE TO BE IN ACCORDANCE WITH TITLE 49 OF THE CODE OF FEDERAL REGULATIONS.
REMOVE PRESSURE FROM CONTAINER BEFORE LOOSENING CLAMP RING ON DRUM COVER.

PLEASE DECK FOR DAMAGE TO THIS ECUPARITY — DAMAGE MIGT BE HOTED ON THE PROBRIT BILL AT THE THE ECUPARIT IS RECIPED FROM THE CAMPIE.

THIS COUNTRY HAS BEEN CLEAND WITH CLEANING AGAINST AND MAY HAVE RESIDEE LIST IN THE UNIT. PLEASE DECK THE UNIT CHARTULLY
BEFORE FILLIAN. FINAL CLEANING WAY WE REGISTED.

THE DRIVE COVER AND CASKET SHOULD BE CHECKED FOR PROPER ASSEMBLY AND THE CLAMP RING SECURELY TIGHTENEND PROR TO EAR SHIPMENT. IF THE DRIVE COVER INCLUDES A FUSIBLE VENT, IT SHOULD BE INSPECTED AND RECREMPED OR REPLACED IF NECESSARY PRO




DRUM NECK SECTION
SCALE: NONE


AIL ITEM #7


SCALE: NONE

SCALE: NONE

NOTE: IF APPLICABLE, PER TITLE 49CFR, BOTH THE 22 1/2" CLOSURE CLAMP RING, BOLT, NUT AND THE 2" BUNG PLUG MUST BE TIGHTENED TO A TORQUE OF 30 Ft.—Ibs. TO SATISFY THE PERFORMANCE REQUIREMENTS.







NOTE: BOTTOM SUMP SLOPES 1/2" TOWARDS OPENING

NOTES:

- 1. REMOVE ALL BURRS AND SHARP EDGES.
- 2. TANK FABRICATED W/2" RADIUS CORNERS AND HIGH CONTOUR LEGS.
- 3. MATERIAL OF CONSTRUCTION IS 304 S.S. AND NOTED.
- 4. INSIDE OF TANK TO BE WIPED CLEAN AT FINAL ASS'Y.
- 5. WARRANTY TAG TO BE WIRED TO CLAMP RING AT FINAL ASS'Y.



P.O. Box 240072 8700 West Bradley Road Milwaukee, WI 53224 800·333·3331 **PHONE** 800·563·8848 **FAX**

info@jmesales.com **E-MAIL** www.JMEsales.com **WEB**